




MICHAEL R. STYLER Executive Director

JOHN R. BAZA Division Director

Inspection Report Minerals Regulatory Program Report Date: September 29, 2006



Mine Name: Dolomite Stone Operator Name: Steven Laub

8275 South 1975 Road

Permit number: S/053/050 Date: September 13, 2006 Time: 4:00 PM

Humansville, Missouri	
Inspector(s): Doug Jensen	
Other Participants: None	
Mine Status: Inactive	Weather: Clear, hot
Elements of Inspection	Evaluated Comment Enforcement
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Concurrent Reclamation Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes) Water Impoundments Soils Revegetation Air Quality Other 	
Purpose of Inspection: Inspected the site while in the area.	
Directions to Site: See previous inspection report.	
Inspection Summary: The site is unchanged since my last inspection in this spring impacted the site. The road into the site is still an area in Butcher Knife Canyon.	
Conclusions and Recommendations: I will continue to monitor the site when I am in t	he area.
Inspector's Signature Language Lenser	Date: 9/28/06
dj.pb cc: Steven Laub Russ Schreiner, BLM, St George FO UTU-74914	

O:\M053-Washington\S0530050-DolomiteStone\inspections\09142006insp.doc